

P06



Speed bump causes vehicles to swerve into the bike lane. Installing a wand here would prevent this.