

P04

There is no discernable reason for this narrowing of the bike lane. White lines should be redone and the wands repositioned to create a uniformly wide bike lane.

